

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403218529

Date Received:

11/03/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10774

Name of Operator: SUMMIT OIL & GAS LLC

Address: PO BOX 983038

City: PARK CITY State: UT Zip: 84098

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

dylan.edwardson@state.co.us

bp@s-companies.com

Sam Bradley

970-593-8626

sb@s-companies.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697503871

Inspection Date: 04/08/2022

FIR Submit Date: 04/21/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SUMMIT OIL & GAS LLC

Company Number: 10774

Address: PO BOX 983038

City: PARK CITY State: UT Zip: 84098

LOCATION - Location ID: 465272

Location Name: Castor 7-59 Number: 12 County: _____

Qtrqr: SWSE Sec: 12 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583298 Longitude: -103.925119

FACILITY - API Number: 05-123-00 Facility ID: 465272

Facility Name: Castor 7-59 Number: 12

Qtrqr: SWSE Sec: 12 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.583298 Longitude: -103.925119

CORRECTIVE ACTIONS:

1 ☒ CA# 161186

Corrective Action: The previous corrective action remains open. COGCC Staff is contemplating the next steps to be performed and will be in coordination with the Operator.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/02/2022

Operator Comment: Please see attached topsoil site assessment report. After reviewing the discrepancy between what the construction company reported and the drone calculation from COGCC, Summit elected to hire a third party (RPG Resources) to verify the COGCC volume. The construction company was fired and a different construction

company was hired for all future location construction as the topsoil volume stockpiled by the construction company is approximately 50% of what was reported to the operator and the COGCC.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Operator complied with the previous corrective action to perform a topsoil site assessment which demonstrated that the Operator failed to salvage approximately 50% of the topsoil during construction operations.

NOTE: COGCC Staff will be issuing a follow up corrective action inspection requiring the Operator to import the amount of topsoil that was not salvaged.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached topsoil site assessment report. After reviewing the discrepancy between what the construction company reported and the drone calculation from COGCC, Summit elected to hire a third party (RPG Resources) to verify the COGCC volume. The construction company was fired and a different construction company was hired for all future location construction as the topsoil volume stockpiled by the construction company is approximately 50% of what was reported to the operator and the COGCC.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sam Bradley

Signed: _____

Title: Partner

Date: 11/3/2022 1:38:09 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403218529	FIR RESOLUTION SUBMITTED
403218601	Topsoil Site Assessment Report

Total Attach: 2 Files