

# Inspection Photos

12/19/2022

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location #334431

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location #334431



December 19, 2022



December 19, 2022

**Photo 1:** Photos 1-2 taken from the south end of the Location. Photos provide an overview of the location from west, northwest, northeast to east.

# Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334431



December 19, 2022



December 19, 2022

**Photo 2:** See comment under photo 1.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334431



**Photo 3:** Photo shows cut slopes on the south end of the Location- slopes appear to be vegetated and stabilized.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location #334431



**Photo 4:** Tank battery facility.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334431



**Photo 5:** Photos examples showing various holes observed throughout the entire liner at the tank battery.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334431



**Photo 6:** Soil stockpile on the west end of the Location.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location #334431



**Photo 7:** Photo taken from the soil stockpile on the northwest end of the Location, facing east and southeast. Photos show areas on the north end of the Location that have not been reclaimed in accordance with 1003 requirements- fill slopes remain evident, soils are compacted, gravel/road base was not removed and soils replaced. Yellow arrows in photo left shows production equipment (wells, separators).

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location #334431



December 19, 2022

**Photo 8:** Photo taken from the north end of the Location, facing northwest. Photo shows areas not needed for production have not been reclaimed- gravel/road base remains evident; areas have not been decompacted, recontoured and reclaimed per 1003 rules.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location #334431



**Photo 9:** Photo taken from the north end of the Location. Photo shows example of Undesirable Plant Species observed- Species observed include Halogeton, and Russian thistle.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location #334431



**Photo 10:** Google earth aerial image of the Location. Red polygon provides examples are areas not needed for production requiring interim reclamation. Areas ~1 acre in size.