

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403177467

Date Received:
09/26/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 68710
Name of Operator: PETERSON ENERGY OPERATING INC
Address: PO BOX 2169
City: LOVELAND State: CO Zip: 80539-2169
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Graber, Nikki</u>		<u>nikki.graber@state.co.us</u>
<u>Peterson, Andy</u>	<u>970-669-7411</u>	<u>andy.peterson@petersonenergy.com</u>
<u>Dornbos, Ryan</u>		<u>ryan@petersonenergyoperating.com</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
<u>Deranleau, Greg</u>		<u>greg.deranleau@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688313134
Inspection Date: 09/17/2022 FIR Submit Date: 09/19/2022 FIR Status: _____

Inspected Operator Information:

Company Name: PETERSON ENERGY OPERATING INC Company Number: 68710
Address: PO BOX 2169
City: LOVELAND State: CO Zip: 80539-2169

LOCATION - Location ID: 317477

Location Name: CHURCH-63S51W Number: 25NENE County: WASHINGTON
Qtrqr: NENE Sec: 25 Twp: 3S Range: 51W Meridian: 6
Latitude: 39.768690 Longitude: -103.033088

FACILITY - API Number: 05-121-00 Facility ID: 295348

Facility Name: CHURCH Number: 41B-25
Qtrqr: NENE Sec: 25 Twp: 3S Range: 51W Meridian: 6
Latitude: 39.768690 Longitude: -103.033088

CORRECTIVE ACTIONS:

1 ☒ CA# 164658

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 10/19/2022

Response: CA COMPLETED

Date of Completion: 09/19/2022

Operator Comment: Secondary containment was repaired on 09/19/2022.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Inspector with check for berm compaction and that the berms north of treater shed during reinspection

2  CA# 164659

Corrective Action: Form 19I, document number 403169688 was submitted and is in process. Operator is to shut in well that is producing and clean up free oil. Contact COGCC EPS.

Date: 09/23/2022

Response: CA COMPLETED

Date of Completion: 09/22/2022

Operator Comment: The de minimus skim of oil reported on soil was located, scraped up and removed. The soil collected amounted to a couple shovel fulls.

COGCC Decision: **Not Approved**

COGCC Representative: Inspector observed more than a couple shovels of stained soil after the spill so during re-inspection will check if all areas were cleanup. The producing well was never shut in as far as the inspection knows.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: _____

Title: Petroleum Engineer

Date: 9/26/2022 12:49:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403177467	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files