

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403205009

Date Received:

10/21/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Victoria Dizghinjili

Phone

303-825-4822

Email

vdizghinjili@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688313264

Inspection Date: 10/10/2022

FIR Submit Date: 10/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

LOCATION - Location ID: 320756

Location Name: STATE-64S62W Number: 14SWNE County: ARAPAHOE

Qtrqr: SWNE Sec: 14 Twp: 4S Range: 62W Meridian: 6

Latitude: 39.704261 Longitude: -104.291482

FACILITY - API Number: 05-005- -00 Facility ID: 204815

Facility Name: STATE Number: 14-32

Qtrqr: SWNE Sec: 14 Twp: 4S Range: 62W Meridian: 6

Latitude: 39.704261 Longitude: -104.291482

CORRECTIVE ACTIONS:

1 ☒ CA# 165213

Corrective Action: Calibrate gas metering equipment annually to comply with rule 430.d.(1).

Date: 11/14/2022

Response: CA COMPLETED

Date of Completion: 10/21/2022

Operator Comment: KPK's production crew began fueling some equipment in execution of KPK's Gas Capture Plan. However, the minimal gas production during these operations was fully consumed by the equipment on location, no selling gas.

COGCC Decision: Not Approved

COGCC Representative:	Two of 3 ECDs on location were burning gas/vapors seen so not all gas was being used on location. A calibration of the meter is required.
-----------------------	---

2	<input checked="" type="checkbox"/> CA# 165214	
Corrective Action:	Install or repair required BMPs per Rule 1002.f(2)C	Date: 10/21/2022
Response:	CA COMPLETED	Date of Completion: 10/21/2022
Operator Comment:	BMPs have been repaired. Please see attached pictures.	
COGCC Decision:	Approved pending re-inspection	
COGCC Representative:	Inspector will do a re-inspection. Photo shows that the waddles around the stained soil pile from the excavation were lined out however it looks like the cattle can still get into the stained soil.	

3	<input checked="" type="checkbox"/> CA# 165215	
Corrective Action:	Lack of pit liner or pit liner compromised (Rule 910). IMMEDIATE NOTIFICATION TO THE OPERATOR Reduce fluid level in pit, contact COGCC EPS staff for directives.	Date: 10/21/2022
Response:	CA COMPLETED	Date of Completion: 10/21/2022
Operator Comment:	Corrective action was completed. Please see attached pictures.	
COGCC Decision:	Approved pending re-inspection	
COGCC Representative:	Inspector will re-inspect the pit liner.	

OPERATOR COMMENT AND SUBMITTAL	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Victoria Dizghinjili	Signed: _____
Title: Engineering Tech	Date: 10/21/2022 1:19:10 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403205009	FIR RESOLUTION SUBMITTED
403205131	CA completed PIC1
403205135	CA completed PIC2
403205136	CA completed PIC3

Total Attach: 4 Files