

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403279417

Date Received:

01/04/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699805329

Inspection Date: 12/14/2022

FIR Submit Date: 12/15/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 322510

Location Name: MOBILE-66S92W Number: 20NESW County: _____

Qtrqr: NESW Sec: 20 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.509370 Longitude: -107.693624

FACILITY - API Number: 05-045- -00 Facility ID: 322510

Facility Name: MOBILE-66S92W Number: 20NESW

Qtrqr: NESW Sec: 20 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.509370 Longitude: -107.693624

CORRECTIVE ACTIONS:

1 ☒ CA# 166583

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 10/28/2022

Response: CA COMPLETED

Date of Completion: 01/02/2023

Operator Comment: The Production Field Supervisor has inspected this location and has deemed it is sufficiently stable for ongoing operations. Ruts are to be expected during muddy / wet conditions. The ruts will be bladed and filled in once the location has sufficiently dried out. Storm water BMPs are intact and functioning correctly around the pad and along the access road. The corrective action has been addressed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The Production Field Supervisor has inspected this location and has deemed it is sufficiently stable for ongoing operations. Ruts are to be expected during muddy / wet conditions. The ruts will be bladed and filled in once the location has sufficiently dried out. Storm water BMPs are intact and functioning correctly around the pad and along the access road. The corrective action has been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 1/4/2023 12:02:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403279417	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files