

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403284759

Date Received:
01/10/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10611

Name of Operator: LONGS PEAK RESOURCES LLC

Address: 2727 ALLEN PARKWAY SUITE 1850

City: HOUSTON State: TX Zip: 77019

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brandi Terry

832-748-0912

egeiser@juncap.com

brandi.terry@boomtownoil.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693701044

Inspection Date: 12/12/2022

FIR Submit Date: 12/12/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LONGS PEAK RESOURCES LLC

Company Number: 10611

Address: 2727 ALLEN PARKWAY SUITE 1850

City: HOUSTON State: TX Zip: 77019

LOCATION - Location ID: 452516

Location Name: Oxnard East Number: 0607-8CH County: _____

Qtrqtr: SESE Sec: 31 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.958630 Longitude: -104.812780

FACILITY - API Number: 05-123-00 Facility ID: 452516

Facility Name: Oxnard East Number: 0607-8CH

Qtrqtr: SESE Sec: 31 Twp: 12N Range: 66W Meridian: 6

Latitude: 40.958630 Longitude: -104.812780

CORRECTIVE ACTIONS:

1 CA# 166515

Corrective Action: Repair and verify integrity of secondary containment. Corrective action date of 1/11/2023 carries over from Inspection 693701041.

Date: 01/11/2023

Response: CA COMPLETED

Date of Completion: 01/06/2023

Operator Comment: The containment was repaired by pulling the damaged section of the wall and replacing with a new piece of metal. The containment wall now has no breaks in it. About 16' was replaced. and 64 sq ft of liner was replaced.

COGCC Decision: _____

COGCC
Representative:

2 CA# 166516

Corrective Action: Use containment device to contain condensate during blowdown. Cleanup oily waste resulting from blowdown.

Date: 01/11/2023

Response: CA COMPLETED

Date of Completion: 01/06/2023

Operator
Comment: Gravel was removed and replaced with new gravel. Pumpers have ben instructed to us a containment device when blowing lines down from now on.

COGCC Decision: _____

COGCC
Representative:

3 CA# 166517

Corrective Action: Clean out sumps in lined containment.

Date: 02/10/2023

Response: CA COMPLETED

Date of Completion: 01/06/2023

Operator
Comment: Sumps were sucked clean and will continue to be monitored going forward to ensure they do not overfill.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brandi Terry

Signed: _____

Title: Regulatory Manager

Date: 1/10/2023 12:04:45 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403284879	CA Repair Photos
-----------	------------------

Total Attach: 1 Files