



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Unable to access location due to lock on gate

Corrective Action: Provide key, combinations, or alternate method of access to comply with rule 204.

Date: 01/05/2023

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 203795 Type: WELL API Number: 001-09355 Status: PR Insp. Status: PR

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On 1/5/23 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Linnebur 6-33                      Company Name-                      API- 05-001-09355                      In Weld/Adams/Denver County Colorado.                      While there, I observed Well Type                      During this inspection the following possible compliance issues were observed:                      Unable to access location due to lock on gate 1/5/23                      Provide key, combinations, or alternate method of access to comply with rule 204.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	medinaj	01/05/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699504366	inspection pictures	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5978056">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5978056</a>