

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 1 – Contractor Photo - 1/10/2023. Backfill in process. Tracking observed on to Godding Hollow Pkwy.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 2 – Contractor Photo - 1/10/2023. Backfill in process.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Latitude: 40.116814
Longitude: -104.967584
Elevation: 1504.22±4 m
Accuracy: 87.8 m
Azimuth: 257° (W)
Pitch: -18.6° (3.8°)
Time: 01-10-2023 15:32
Note: Grant Tank Battery

Powered by AngleCam

Photo 3 – Contractor Photo - 1/10/2023. Backfill in process.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 4 – Contractor Photo - 1/10/2023. Tracking observed on to Godding Hollow Pkwy. Tracking pad unmaintained.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 5 – Contractor Photo - 1/10/2023. Tracking observed on to Godding Hollow Pkwy. Tracking pad unmaintained.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Latitude: 40.116761
Longitude: -104.968324
Elevation: 1503.52±4 m
Accuracy: 13.8 m
Azimuth: 321° (NW)
Pitch: -10.9° (1.7°)
Time: 01-10-2023 15:33
Note: Grant Tank Battery

Powered by AngleSam

Photo 6 – Contractor Photo - 1/10/2023. Tracking observed on to Godding Hollow Pkwy. Tracking pad unmaintained.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 7 – Contractor Photo - 1/9/2023. Unused PBV remains on site.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 8 – Contractor Photo - 1/9/2023. Backfill in process.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 9 – Contractor Photo - 1/9/2023. Tracking observed on to Godding Hollow Pkwy. Tracking pad unmaintained.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 10 – Contractor Photo - 1/8/2023. Backfill in process.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 11 – Contractor Photo - 12/21/2022. Backfill progress.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 12 – Contractor Photo - 12/21/2022. Tracking pad unmaintained.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 13 – Contractor Photo - 12/20/2022. Backfill progress.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 14 – Contractor Photo - 12/20/2022. Tracking observed on to Godding Hollow Pkwy.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 15 – Contractor Photo - 12/19/2022. Backfill progress.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 16 – Contractor Photo - 12/19/2022. Tracking observed on to Godding Hollow Pkwy.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 17 – Contractor Photo - 12/16/2022. Backfill progress.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 18 – Contractor Photo - 12/16/2022. Tracking observed on to Godding Hollow Pkwy. Tracking pad unmaintained.

Inspection Photos
Grant Tank Battery
Remediation Project No 12158



Photo 19 – Contractor Photo – 12/1/2022. Excavation prior to backfill.