

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403269996

Date Received:
12/22/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Daniel Benedict</u>	<u>303-902-1593</u>	<u>dbenedict@locin.energy</u>
<u>Humberto Sirvent</u>		<u>hsirvent@locinoil.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 696204451
Inspection Date: 12/05/2022 FIR Submit Date: 12/06/2022 FIR Status: _____

Inspected Operator Information:

Company Name: LOCIN OIL CORPORATION Company Number: 51130
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 322339

Location Name: GOVERNMENT-66S104W Number: 34NENE County: _____
Qtrqtr: NENE Sec: 34 Twp: 6S Range: 104W Meridian: 6
Latitude: 39.499473 Longitude: -108.967543

FACILITY - API Number: 05-045-00 Facility ID: 322339

Facility Name: GOVERNMENT-66S104W Number: 34NENE
Qtrqtr: NENE Sec: 34 Twp: 6S Range: 104W Meridian: 6
Latitude: 39.499473 Longitude: -108.967543

CORRECTIVE ACTIONS:

1 CA# 166433

Corrective Action: Comply with 1002.f.; Implement and maintain BMPs to control stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation on access road. Ensure controls are implemented in accordance with good engineering practices and maintained in proper functioning condition; regrading alone will not be sufficient to stabilize road and manage runoff.

Date: 09/13/2022

Response: CA COMPLETED Date of Completion: 12/21/2022

Stormwater and erosion control BMPs have been implemented along the access road per Rule1002.f. Please see attached photos.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection. Based on photo documentation provided, work to address the corrective action appears to have been performed, however it is unclear if BMPs have been installed per good engineering requirements in accordance with Rule 1002.f. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action has been completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Melanie Adams

Signed: _____

Title: Agent

Date: 12/22/2022 2:33:23 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403269996	FIR RESOLUTION SUBMITTED
403270048	Location photo
403270052	Location photo
403270058	Location photo
403270060	Location photo

Total Attach: 5 Files