

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403301294

Date Received:
01/25/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

_General

sninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693904113

Inspection Date: 01/19/2022

FIR Submit Date: 01/21/2022

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 312063

Location Name: BONDAD 33-9-N33N9W Number: 6SENE County: LA PLATA

Qtrqr: SENE Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.135877 Longitude: -107.861612

FACILITY - API Number: 05-067-00 Facility ID: 259759

Facility Name: HUNGERFORD A Number: 2

Qtrqr: SENE Sec: 6 Twp: 33N Range: 9W Meridian: N

Latitude: 37.135877 Longitude: -107.861612

CORRECTIVE ACTIONS:

1 CA# 159302

Corrective Action: -Control weeds by 6/1/2022.
-Revegetation needs to be installed within the southern project area by 5/1/2022.

Date: 05/01/2022

Response: CA COMPLETED

Date of Completion: 01/25/2023

Operator Comment: Treated noxious weeds with chemical treatment as documented in FIRR #693904113 and #403121809. The area designated for reseeding is outside the area of wellsite and is under the landowner's control. See the attached aerial with the pad dimensions overlaid. Using the tree as a reference point, the southern area called out for correction is not part of the operator's built pad (flat or slopes). Referencing LOGOS's response FIRR #403024660 and its photos LOGOS appears to have addressed this inspection item.

COGCC Decision: _____

COGCC
Representative:

2 CA# 159303

Corrective Action: Stormwater (BMPs) and erosion controls (ie: mulch) need to be installed in the southern project area by 5/1/2022. Stormwater and erosion controls need to be installed and maintained until area is stabilized with desirable perennial vegetation.

Date: 05/01/2022

Response: CA COMPLETED

Date of Completion: 01/25/2023

Operator Comment: The area designated for stormwater controls is outside the area of wellsite and is under the landowner's control. See the attached aerial with the pad dimensions overlayed. Using the tree as a reference point, the southern area called out for correction is not part of the operator's built pad (flat or slopes). Referencing LOGOS's response FIRR #403024660 and its photos LOGOS appears to have addressed this inspection item.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The area designated for operator response is outside the operator's built pad (including slopes).

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Katherine Feir

Signed: _____

Title: Compliance Coordinator

Date: 1/25/2023 11:07:12 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number Description

403301317	map and aerial showing extent of pad
-----------	--------------------------------------

Total Attach: 1 Files