

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403302335

Date Received:

01/25/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490

Name of Operator: ST CROIX OPERATING INC

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Melnychenko, Paul

(303) 489-9298

stcroixexp@aol.com

Andy Peterson

970-203-4263

Andy@PEOperating.com

Ryan Dornbos

Ryan@PEOperating.com

Arthur, Denise

denise.arthur@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105675

Inspection Date: 01/09/2023

FIR Submit Date: 01/17/2023

FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC

Company Number: 81490

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 482780

Location Name: Horseshoe

Number: 1

County: _____

Qtrqtr: NENE

Sec: 27

Twp: 3S

Range: 49W

Meridian: 6

Latitude: 39.768700

Longitude: -102.843070

FACILITY - API Number: 05-121-

-00

Facility ID: 482780

Facility Name: Horseshoe

Number: 1

Qtrqtr: NENE

Sec: 27

Twp: 3S

Range: 49W

Meridian: 6

Latitude: 39.768700

Longitude: -102.843070

CORRECTIVE ACTIONS:

1 CA# 167022

Corrective Action:

Date: 01/24/2023

Operator shall submit results from soil pits and proposed soil sample sites as described in Topsoil sampling map (Doc #402948673; page 6) to determine and evaluate topsoil depths as measured in the field. Additionally, Operator shall provide documentation for the quantity/volume of all topsoil salvaged during the construction phase of this location to ensure compliance with topsoil salvage requirements.

Submittal of this information does not indicate compliance with the topsoil salvage requirement of Rule 1002.b.

Response: CA COMPLETED

Date of Completion: 01/09/2023

Operator Comment: St. Croix stripped and stockpiled the top 6' from the 300'x300' working pad surface per the submitted topsoil protection plan. 1,667 yards of topsoil were stockpiled. The soil sampling referenced in Doc #402948673, pg 6, is described in the attached reclamation plan.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 167023

Corrective Action: Comply with Rule 1002.c. Corrective action date is the date the location was observed out of compliance.

Date: 01/09/2023

Response: CA COMPLETED

Date of Completion: 01/09/2023

Operator Comment: The site was adequately protected against wind and water erosion at all times. There is no evidence that any soils exited the site due to either wind or water erosion. The location has seen three significant snow storms since construction began. Runoff from these storms has not caused any off-location sediment transfer. This location will not be receiving any significant rain events during the period between construction and conclusion of reclamation. At present, the topsoil piles are frozen. Neither wind or water erosion will be occurring.

COGCC Decision: _____

COGCC Representative: _____

3 CA# 167024

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

Date: 01/09/2023

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Response: CA COMPLETED

Date of Completion: 01/09/2023

Operator Comment: BMPs (ditch, berm, track packing) were constructed from salvaged topsoil and were taken down in part as necessary to return the topsoil to its original location. Reclamation will be concluded prior to soils thawing. Soil transport off location has not and will not occur due to frozen soils and low slope angle on this site.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The Horseshoe #1 well had a short duration drilling period and was drilled and abandoned. St. Croix plans to conclude reclamation activities by returning the topsoil to its original location and reseeding as soon as weather permits.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: _____

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403302362	Topsoil Plan

Total Attach: 1 Files