

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/17/2023

Submitted Date:

01/19/2023

Document Number:

690203806

**FIELD INSPECTION FORM**Loc ID 309227 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
290428	WELL	PR	07/13/2007	CBM	071-09267	BLACK GOLD 32-33	RI
301143	PIT	AC	01/07/2010		-	BLACK GOLD 32-33	AC

**General Comment:**

This is a follow up location inspection.  
See attached photos and additional details within this report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective ActionL		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: Stained soils have been cleaned up and a secondary container was installed.☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 301143Lat: 37.301950Long: -104.784600Reference Point: Other: Length: Width: **Lining:**Liner Type: PlasticLiner Condition: Inadequate

Comment:

There are holes in the pit liner. The water level has not been lowered since previous inspection. A sign was placed at the pit indicating pit closure in process however, no form 27 has been submitted. Previous corrective action remains and needs to be performed immediately.

Corrective Action

Pit liner compromised (Rule 910). Reduce fluid level in pit. Replace Pit Liner or Submit Form 27 for Pit Closure.

Date: 11/11/2022**Fencing:**

Fencing Type:

Fencing Condition:

Comment: Corrective Action Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Action Date: 

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403295853	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5989419">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5989419</a>
690203807	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5989414">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5989414</a>