



Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #1 South side of tank battery. This area has an engineered liner. Crews chipped up frozen water and were placing it into a truck for disposal in milner.





Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

**Photo #2 spill started from valve in center of this picture (can not really see it, see Photo #4). Photos 1-4 show the area were Ice was chipped by hand and loaded into a side dump for offsite disposal as E&P waste.**



Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

**Photo #3 Photos 1-4 show the area were Ice was chipped by hand and loaded into a side dump for offsite disposal as E&P waste.**





Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #4 The Valve at left of photo is the valve that froze and released the produced water. Photos 1-4 show the area were Ice was chipped by hand and loaded into a side dump for offsite disposal as E&P waste.



Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #5 ice to right of tank has yet to be removed.





Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #6 frozen Produced water





Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #7 north side of tank battery. Frozen produced water.





Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #8 east side of tank battery





**Photo #9 inside tank battery**

**Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel**





Inspection Photos  
Spill 483729  
1/26/23  
All Photos taken  
by Kris Neidel

Photo #10 west side of tank battery

