

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403309599

Date Received:
02/01/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 68710
Name of Operator: PETERSON ENERGY OPERATING INC
Address: PO BOX 2169
City: LOVELAND State: CO Zip: 80539-2169
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Leonard, Mike		mike.leonard@state.co.us
Graber, Nikki		nikki.graber@state.co.us
Deranleau, Greg		greg.deranleau@state.co.us
Dornbos, Ryan		ryan@petersonenergyoperating.com
Peterson, Andy	970-669-7411	Andy@PetersonEnergyOperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688313134
Inspection Date: 09/17/2022 FIR Submit Date: 09/19/2022 FIR Status:

Inspected Operator Information:

Company Name: PETERSON ENERGY OPERATING INC Company Number: 68710
Address: PO BOX 2169
City: LOVELAND State: CO Zip: 80539-2169

LOCATION - Location ID: 317477

Location Name: CHURCH-63S51W Number: 25NENE County: WASHINGTON
Qtrqr: NENE Sec: 25 Twp: 3S Range: 51W Meridian: 6
Latitude: 39.768690 Longitude: -103.033088

FACILITY - API Number: 05-121-00 Facility ID: 295348

Facility Name: CHURCH Number: 41B-25
Qtrqr: NENE Sec: 25 Twp: 3S Range: 51W Meridian: 6
Latitude: 39.768690 Longitude: -103.033088

CORRECTIVE ACTIONS:

1 CA# 164658

Corrective Action: Repair or install berms or other secondary containment devices per Rule 603.o.

Date: 10/19/2022

Response: CA COMPLETED

Date of Completion: 09/19/2022

Operator Comment: Secondary containment was repaired on 09/19/2022. The well was shut in, and restarted once repaired.

COGCC Decision: _____

COGCC Representative: _____

2 CA# 164659

Corrective Action: Form 19I, document number 403169688 was submitted and is in process. Operator is to shut in well that is producing and clean up free oil. Contact COGCC EPS.

Date: 09/23/2022

Response: CA COMPLETED

Date of Completion: 09/22/2022

Operator Comment: The de minimus skim of oil reported on soil was located, scraped up and removed. The soil collected amounted to a couple shovel fulls.

In response to the denial of our initial FIRR filing:
Multiple visits and inspections to the site were completed at the time of release to verify any amounts of oil that were present were removed and disposed of. The resulting volume with staining was as stated previously adding up to couple shovels worth of material. When collecting, the only soil collected was the stained soil which was just the top one-eighth inch or so in each of these areas. Additionally I recall speaking over the phone to the inspector and informing that we would shut the well in until the berm was repaired and turn it back to PR once complete.

COGCC Decision: _____

COGCC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: Please correct email for Andy Peterson in your system. andy.peterson@petersonenergy.com is NOT a valid email and is not on record with the COGCC. Notifications sent to this email will not reach Peterson Energy Operating, Inc. I have corrected this email in the contacts section.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: _____

Title: Petroleum Engineer

Date: 2/1/2023 4:51:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files