

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403235141

Date Received:

11/21/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

JACKSON C MICHAEL

Phone

281-800-7713

Email

c.jackson@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 690203458

Inspection Date: 10/04/2022

FIR Submit Date: 10/05/2022

FIR Status: _____

Inspected Operator Information:

Company Name: AMOCO PRODUCTION COMPANY

Company Number: 2500

Address: P O BOX 3092 ROOM 2.554

City: HOUSTON State: TX Zip: 77253-309

LOCATION - Location ID: 386457

Location Name: MGP ENTERPRISES "A"-634S66W Number: 9NWNE County: LAS ANIMAS

Qtrqr: NWNE Sec: 9 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.105024 Longitude: -104.780336

FACILITY - API Number: 05-071-00 Facility ID: 217318

Facility Name: MGP ENTERPRISES A Number: 4

Qtrqr: NWNE Sec: 9 Twp: 34S Range: 66W Meridian: 6

Latitude: 37.105024 Longitude: -104.780336

CORRECTIVE ACTIONS:

1 ☒ CA# 164975

Corrective Action: Comply with 1004 Rules.

Date: _____

Response: CA COMPLETED

Date of Completion: 11/07/2022

Operator Comment: The landown has expressed his desire to leave the road and well site as is. He has requested a waiver so that a 502.b variance can be pursued.

COGCC Decision: Not Approved

| | | | |
|-------------------------------------|---|--|--------------------------------|
| COGCC Representative: | Corrective action to comply with 1004 has not been completed. COGCC acknowledges that a 502 b. request has been submitted however, the location remains out of compliance with 1004 Rules unless a variance of the rule is obtained. | | |
| 2 | ✖ | CA# 164976 | |
| Corrective Action: | | Install or repair required BMPs per Rule 1002.f.(2) | Date: _____ |
| Response: | | CA COMPLETED | Date of Completion: 11/07/2022 |
| Operator Comment: | | Due to time constraint and pending incimate weather the site was stabilized to prevent erosion during the winter. Further work will be performed during the sping. | |
| COGCC Decision: Not Approved | | | |
| COGCC Representative: | | Corrective action to comply with 1002.f.(2) has not been completed. The photos provided show erosion was not repaired and there are areas not stabilized. | |

| | |
|---|--|
| OPERATOR COMMENT AND SUBMITTAL | |
| Comment: | This site has restricted access by the landowner who granted us work access the 1st week of November to comply with the FIR 690203458 corrective action install or repair BMP per Rule 1002.f.(2). |
| I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete. | |
| Print Name: C. Michael Jackson | Signed: _____ |
| Title: Liability Manager | Date: 11/21/2022 5:33:33 AM |

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| Document Number | Description |
|-----------------|---------------------------|
| 403235141 | FIR RESOLUTION SUBMITTED |
| 403235143 | MGP Field Activity Report |

Total Attach: 2 Files