

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403305126

Date Received:
02/03/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Brent Bongers

3619355633

bbongers@impetroresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105685

Inspection Date: 01/13/2023

FIR Submit Date: 01/19/2023

FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 558 CASTLE PINES PKWY UNIT B-4

City: CASTLE PINES State: CO Zip: 80108

LOCATION - Location ID: 317093

Location Name: STENNETT-62N49W Number: 21SWNE County: _____

Qtrqr: SWNE Sec: 21 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.128370 Longitude: -102.858180

FACILITY - API Number: 05-121-

-00

Facility ID: 317093

Facility Name: STENNETT-62N49W Number: 21SWNE

Qtrqr: SWNE Sec: 21 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.128370 Longitude: -102.858180

CORRECTIVE ACTIONS:

1 CA# 167076

Corrective Action: Properly dispose of oily waste in accordance with 905.e.

Date: 02/03/2023

Response: CA COMPLETED

Date of Completion: 02/03/2023

Operator
Comment:

Oily waste sent to Pawnee. Manifest 147642

COGCC Decision:

COGCC
Representative:

2 CA# 167077

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 02/03/2023

Response: CA COMPLETED

Date of Completion: 01/27/2023

Operator
Comment: completed

COGCC Decision:

COGCC
Representative:

3 CA# 167078

Corrective Action: Install sign to comply with Rule 605.d.

Date: 02/19/2023

Response: CA COMPLETED

Date of Completion: 02/19/2023

Operator
Comment: signs ordered and will be installed by 2/19/2023

COGCC Decision:

COGCC
Representative:

4 CA# 167079

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance.

Date: 01/13/2023

Response: CA COMPLETED

Date of Completion: 02/01/2023

Operator
Comment: Due to winter weather and steep slopes it's too dangerous to heavy equipment on pit banks until the soil dries out. We've repaired what we could.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brent Bongers

Signed:

Title: President/COO

Date: 2/3/2023 12:29:50 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files