

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403312318

Date Received:

02/04/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490

Name of Operator: ST CROIX OPERATING INC

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Trisha Fanning

tfanning@ardorenvironmental.com

Andy Peterson

Andy@Petersonenergyoperating.com

Melnychenko, Paul

(303) 489-9298

stcroixexp@aol.com

Ryan Dornbos

Ryan@Petersonenergyoperating.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105682

Inspection Date: 01/17/2023

FIR Submit Date: 01/19/2023

FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC

Company Number: 81490

Address: P O BOX 13799

City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 474453

Location Name: ALICE SEEDORF Number: 1 County: _____

Qtrqr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.123560 Longitude: -102.843830

FACILITY - API Number: 05-121-00 Facility ID: 474453

Facility Name: ALICE SEEDORF Number: 1

Qtrqr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6

Latitude: 40.123560 Longitude: -102.843830

CORRECTIVE ACTIONS:

2 CA# 167063

Corrective Action: Comply with Rule 1002.f.(2) to install and maintain BMPs in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance as the location should be in compliance at all times.

Date: 01/17/2023

Response: CA COMPLETED

Date of Completion: 01/17/2023

Operator
Comment:

The topsoil pile from the original 5" of material stripped was track packed previously, is now frozen, and serves as a BMP protecting the north side of the second topsoil pile. The topsoil piles contain significant clay and are frozen and thus are not subject to wind erosion at this time of year.

2/4/2023 Response

St. Croix restates that interim or final reclamation will occur as soon as weather conditions allow and also restates that frozen soil conditions provide adequate soil compaction to ensure site conditions and controls are adequate and in place to effectively manage stormwater per Rule 1002.f (2) (D).

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed:

Title: Petroleum Engineer

Date: 2/4/2023 11:56:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

--	--

Total Attach: 0 Files