

OGCC FORM 4
Rev 8/89STATE OF COLORADO
OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES

SUBMIT ORIGINAL AND 1 COPY



FOR OFFICE USE ONLY			
ET	FE	UC	SE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

<input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> COALBED METHANE <input type="checkbox"/> INJECTION WELL <input type="checkbox"/> OTHER		5 FEDERAL INDIAN OR STATE LEASE NO
2 NAME OF OPERATOR Western Operating Company		6 PERMIT NO 66-310
3 ADDRESS OF OPERATOR 518 - 17th St., Suite 1680		7 API NO 05-061-5144
CITY Denver	STATE CO	8 WELL NAME Harrison
ZIP CODE 80202		9 WELL NUMBER No. 2
4 LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below) At surface 660' FNL & 660' FEL of Section 9 At proposed prod zone Same		10 FIELD OR WILDCAT Brandon
12 COUNTY Kiowa		11 QTR QTR SEC. T.R. AND MERIDIAN NENE Section 9 T19S-R45W

Check Appropriate Box To Indicate Nature of Notice, Report or Notification

13A. NOTICE OF INTENTION TO:

- ☒ PLUG AND ABANDON
- ☐ MULTIPLE COMPLETION
- ☐ COMMINGLE ZONES
- ☐ FRACTURE TREAT
- ☐ REPAIR WELL
- ☐ OTHER

13B. SUBSEQUENT REPORT OF:

- ☐ FINAL PLUG AND ABANDONMENT (SUBMIT 3RD PARTY CEMENT VERIFICATION AND JOB LOG)
- ☐ ABANDONED LOCATION (WELL NEVER DRILLED - SITE MUST BE RESTORED WITHIN 6 MONTHS)
- ☐ REPAIRED WELL
- ☐ OTHER

*Use Form 3 - Well Completion or Recompletion Report and Log
for subsequent reports of Multiple/Commungled Completions
and Recompletions

13C. NOTIFICATION OF:

- ☐ SHUT-IN TEMPORARILY ABANDONED (DATE _____) (REQUIRED EVERY 6 MONTHS)
- ☐ PRODUCTION RESUMED (DATE _____)
- ☐ LOCATION CHANGE (SUBMIT NEW PLAT)
- ☐ WELL NAME CHANGE
- ☐ OTHER

14 DESCRIBE PROPOSED OR COMPLETED OPERATIONS ON THIS FORM (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent

15 DATE OF WORK Third (3rd) Quarter, 1996

1. Set CIBP @ 4500'±. Spot 2 sx cement on top of CIBP. Load csg w/water. If hole doesn't load spot 10 sx cement plug @ 1500'±. Let cement set up, load csg w/water.
2. Perf csg w/4 holes @ 1300'±. Set cement retainer @ 1250'±. Mix & pump 115 sx cement through cement retainer. Leave 15 sx inside casing.
3. Perf 4 holes in csg @ 240'. Mix & pump 50 sx cement. Pump 25 sx through perfs @ 240'. Leave 25 sx inside csg. 260'
4. Set 10 sx plug @ surface. Put 5 sx inside 8-5/8" & 5 sx inside 5-1/2". Cut off 8-5/8" & 5-1/2" csg 4'+below ground level. Weld on plate 1/4" or thicker reading Harrison #2 - NENE Section 9-T19S-R45W.
5. Reclaim location.

16. I hereby certify that the foregoing is true and correct

SIGNED

TELEPHONE NO. (303) 893-2438

NAME (PRINT) Steven D. James

TITLE Vice President

DATE March 29, 1996

(This space for Federal or State office use)

APPROVED

TITLE

DATE 4/3/96

CONDITIONS OF APPROVAL, IF ANY: