

Document Number:
403267577

Date Received:
12/23/2022

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 90615 Contact Name: Deborah Abrams
 Name of Operator: TUDEX PETROLEUM INC Phone: (303) 8942100
 Address: 2121 39TH AVE NE UNIT E Fax: _____
 City: CALGARY State: AL Zip: T2E 6R7 Email: deborah.abrams@state.co.us

For "Intent" 24 hour notice required, Name: Medina, Justin Tel: (720) 471-0006
COGCC contact: Email: justin.medina@state.co.us

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-001-08768-00
 Well Name: HI-LAND (OWP) Well Number: 10-G
 Location: QtrQtr: NENE Section: 10 Township: 1S Range: 67W Meridian: 6
 County: ADAMS Federal, Indian or State Lease Number: _____
 Field Name: SPINDLE Field Number: 77900

Only Complete the Following Background Information for Intent to Abandon

Latitude: 39.983411 Longitude: -104.867876
 GPS Data: GPS Quality Value: 0.6 Type of GPS Quality Value: Accuracy in Meters Date of Measurement: 08/10/2020

Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: _____
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
SUSSEX	5232	5303	08/14/2019	B PLUG CEMENT TOP	5150
Total: 1 zone(s)					

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	UNK	24	0	229	175	229	0	VISU
1ST	7+7/8	4+1/2	UNK	10.5	0	5448	375	5448	3846	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 5150 with 2 sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 2500 ft. with 32 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 1500 ft. with 20 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at 1118 ft. with 30 sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 46 sacks half in. half out surface casing from 280 ft. to 0 ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing

Surface Plug Setting Date: 08/16/2019 Cut and Cap Date: 08/16/2019 Number of Days from Setting Surface Plug to Capping or Sealing the Well: 0

*Wireline Contractor: The Perforators

*Cementing Contractor: Duco Inc

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

FIR doc #698600135 includes detailed plugging records.
FIR doc #698600366 has attached GPS screenshot, doc # 698600378.
Plug at 2500' tagged at 2299'
Plug at 1118' tagged 800' (Required to be above 990')
Perf at 280' and pump 46 sacks - Cemented to surface

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Deborah Abrams

Title: OWP Date: 12/23/2022 Email: deborah.abrams@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric

Date: 2/14/2023

CONDITIONS OF APPROVAL, IF ANY:

<u>COA Type</u>	<u>Description</u>
0 COA	

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
2138904	OPERATIONS SUMMARY
403267577	FORM 6 SUBSEQUENT SUBMITTED
403267638	CEMENT JOB SUMMARY
403267639	CEMENT BOND LOG
403270869	WELLBORE DIAGRAM

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)