

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
403320131

Date Received:  
02/14/2023

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

**COGCC INSPECTION SUMMARY:**

FIR Document Number: 702801244

Inspection Date: 02/07/2023

FIR Submit Date: 02/10/2023

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**LOCATION - Location ID: 335076**

Location Name: CLOUGH-66S94W Number: 29SENW County: \_\_\_\_\_

Qtrqr: SENW Sec: 29 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.497105 Longitude: -107.915932

**FACILITY - API Number: 05-045- -00 Facility ID: 335076**

Facility Name: CLOUGH-66S94W Number: 29SENW

Qtrqr: SENW Sec: 29 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.497105 Longitude: -107.915932

**CORRECTIVE ACTIONS:**

1 ☒ CA# 167382

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes.

Date: 01/11/2023

Response: CA COMPLETED

Date of Completion: 02/13/2023

Operator Comment: The injection unit was serviced as previously described in FIR 403302093, but apparently the unit continued to leak. In response to this latest inspection finding, TEP replaced the packing in the heat trace pump and the restarted the system. No leaks were visible after checking the unit on multiple occasions after the repair. Lastly, the heat trace unit uses non-hazardous propylene glycol, and although this material is not an E&P waste, the stained soils have been removed. The corrective action has been completed again.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The injection unit was serviced as previously described in FIRR 403302093, but apparently the unit continued to leak. In response to this latest inspection finding, TEP replaced the packing in the heat trace pump and the restarted the system. No leaks were visible after checking the unit on multiple occasions after the repair. Lastly, the heat trace unit uses non-hazardous propylene glycol, and although this material is not an E&P waste, the stained soils have been removed. The corrective action has been completed again.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 2/14/2023 8:43:10 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number      Description**

403320131	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files