

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2023

Submitted Date:

02/14/2023

Document Number:

702801248

FIELD INSPECTION FORM

Loc ID 323922 Inspector Name: O'Malley, Anna On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED
Findings:
3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
323922	LOCATION	AC			-	CLOUGH-66S94W 29NENE	RI

General Comment:
 On 2/7/2023, Reclamation Specialist O'Malley conducted a field inspection at TEP Rocky Mountain LLC's CLOUGH-66S94W/29NENE Location #323922 in Garfield County, Colorado.
 This is a follow up to inspection #702801105 to assess compliance with a stormwater corrective action. Corrective action from inspection #702801105 has been addressed.
 Refer to the "Stormwater" section of this inspection report for additional details.
 Refer to the photo-documentation attached to this report.
 Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Inspected Facilities

Facility ID: 323922 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Gravel has been installed on the pad surface and portions of the access road immediately adjacent to the pad. Corrective action from inspection #702801105 has been addressed. The location remains partially snow covered. Unable to perform full stormwater inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702801249	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6021357