

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403322477

Date Received:
02/15/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 707800037

Inspection Date: 12/19/2022

FIR Submit Date: 12/20/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335068

Location Name: CLOUGH-66S94W Number: 15SWSW County: _____

Qtrqr: SWS Sec: 15 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.521193 Longitude: -107.880069

FACILITY - API Number: 05-045-00 Facility ID: 335068

Facility Name: CLOUGH-66S94W Number: 15SWSW

Qtrqr: SWS Sec: 15 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.521193 Longitude: -107.880069

CORRECTIVE ACTIONS:

1 CA# 166645

Corrective Action: Install or repair required BMPs in order to achieve stabilization on location

Date: 01/31/2023

Response: CA COMPLETED

Date of Completion: 01/31/2023

Operator Comment: Some ruts on pad are frozen and will need to be bladed / graded smooth when weather and temperatures allow. Several loads of crushed gravel have been added to pad surface and high traffic areas to stabilize soft spots on pad. Corrective action complete. See attached pics.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Some ruts on pad are frozen and will need to be bladed / graded smooth when weather and temperatures allow. Several loads of crushed gravel have been added to pad surface and high traffic areas to stabilize soft spots on pad. Corrective action complete. See attached pics.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Environmental Lead

Date: 2/15/2023 4:49:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403322482	Photo showing fresh gravel on pad
403322483	Photo showing fresh gravel on pad

Total Attach: 2 Files