

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403314806

Date Received:

02/20/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name Phone

Adamczyk, Megan

Email

megan.adamczyk@state.co.us

Doerner, Gina

gina.doerner@ikavenergy.com

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700300549

Inspection Date: 01/09/2023

FIR Submit Date: 01/27/2023

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306900

Location Name: KEATING GAS UNIT-N34N7W Number: 3NWNE County: LA PLATA

Qtrqr: NWNE Sec: 3 Twp: 34N Range: 7W Meridian: N

Latitude: 37.248863 Longitude: -107.619880

FACILITY - API Number: 05-067-00 Facility ID: 275324

Facility Name: KEATING Number: 2

Qtrqr: NWNE Sec: 3 Twp: 34N Range: 7W Meridian: N

Latitude: 37.248863 Longitude: -107.619880

CORRECTIVE ACTIONS:

1 CA# 167264

Corrective Action: Comply with rule 423.b(7) by utilizing readily available measures to reduce periodic nature of noise levels, such as but not limited to, checking bearings, bushings and linkages on equipment, adjusting rod balance on pumping unit, adjusting operating cycle of pumping unit, inspecting, adjusting/upgrading engine muffler or installing noise mitigation in direction of complainant.

Extened CA time given due to seasonal conditions

Date: 02/10/2023

Response: CA COMPLETED

Date of Completion: 02/16/2023

Operator
Comment:

A second muffler was added on 2/8/2023 and maintenance was completed on the pumping unit's clutch and engine on 2/9/2023 addressing the reported location noise. With the recent inclement weather surveying for noise was delayed until 2/16/2023. Results of the noise survey indicate the location is below the threshold found in COGCC Rule 423 and in compliance with COGCC Rule 423(b)(7). See the attached report.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: See the attached noise survey indicating compliance with COGCC Rules.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Katherine Feir

Signed: _____

Title: Compliance Coordinator

Date: 2/20/2023 12:32:24 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403324935	Noise Survey post corrective actions
-----------	--------------------------------------

Total Attach: 1 Files