

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403318797

Date Received:

02/11/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Burchett, Kirby

kirby.burchett@state.co.us

Heil, John

john.heil@state.co.us

Inspection, Terra TEP

970-285-9377

COGCCInspectionReports@terraep.com

Fischer, Alex

alex.fischer@state.co.us

Arauz, Steven

steven.arauza@state.co.us

Schlagenhauf, Mark

mark.schlagenhauf@state.co.us

Kellerby, Shaun

shaun.kellerby@state.co.us

Kirtland, Jeff

jkirtland@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701103681

Inspection Date: 02/10/2023

FIR Submit Date: 02/10/2023

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 383331

Location Name: SPECIALTY RESTAURANTS-67S96W Number: 33NWSW County: _____

Qtrqtr: NWS Sec: 33 Twp: 7S Range: 96W Meridian: 6
W

Latitude: 39.390172 Longitude: -108.121639

FACILITY - API Number: 05-045- -00 Facility ID: 383331

Facility Name: SPECIALTY RESTAURANTS-67S96W Number: 33NWSW

Qtrqtr: NWS Sec: 33 Twp: 7S Range: 96W Meridian: 6
W

Latitude: 39.390172

Longitude: -108.121639

CORRECTIVE ACTIONS:**1** ☒ CA# 167371

Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 912.b.

Date: 02/10/2023

Response: CA COMPLETED

Date of Completion: 02/10/2023

Operator Comment: TEP does not believe that this incident met any of the criteria for a reportable spill or release. A detailed explanation was provided to Alex Fischer on 02/10/23, and is also attached to this response.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 167372

Corrective Action: Document information outlined below on the CA section of COGCC supplemental form 19 spill report to include the following (compliance of COGCC series 1100 flowline rules):

- 1) Outline root cause of failure resulting in spill (1104.k. Integrity Failure Investigation/Operator Determination)
- 2) Measures taken to prevent a recurrence of failure (1102.I Corrosion Control/ 1104.Integrity Management)
- 3) Description of flowline repair work completed (1102.j. Repair)
- 4) Confirm integrity of flowline repairs/ reconnections (via pressure testing) prior to returning flowline to service (1102.j.4 and 1102.O)
- 5) Ensure flowline(s) are isolated and depressurized; associated wells and isolation valves are SI/ OOSLAT to prevent unintentional release per 1102.j.7 (prior to and time of repair).
- 6) Any historical/ out of service flowlines exposed in the excavation must be abandoned per COGCC rule 1105 (ends sealed per 1105.e.4).

Date: 02/28/2023

Response: CA COMPLETED

Date of Completion: 02/11/2023

Operator Comment: TEP does not believe that this incident met any of the criteria for a reportable spill or release, therefore a Form 19 and subsequent Supplemental Form 19 would not be required for an event that is not reportable.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: TEP respectfully submits that this incident does not meet any of the criteria for a reportable spill or release, therefore a Form 19 and subsequent Supplemental Form 19 is not required for an event that is not reportable. Please see attached documentation. Corrective actions #167371 and #167372 have been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Environmental Lead

Date: 2/11/2023 9:40:00 AM

ATTACHMENT LISTView Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403318797	FIR RESOLUTION SUBMITTED
403318801	Correspondence
403318802	SCADA Data
403318803	Excavation and spoils with storm water controls
403318804	Approximate location of gas leak
403318805	Excavating gas line in preparation to conduct repairs

Total Attach: 6 Files