

OIL AND GAS CONSERVATION COMMISSION
DEPARTMENT OF NATURAL RESOURCES
OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Inexco Oil Company		8. FARM OR LEASE NAME Dawson A	
3. ADDRESS OF OPERATOR 308 Lincoln Tower Building Denver, Colorado 80203		9. WELL NO. #4	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface NW NW Section 9-Township 19 South-Range 45 West At proposed prod. zone 660' FNL, 660' FWL		10. FIELD AND POOL, OR WILDCAT Brandon	
14. PERMIT NO. 68319 72-794		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 9 T-19-S, R-45-W	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3893' GR		12. COUNTY Kiowa	13. STATE Colorado

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSISTENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)		(Other)	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Perforated 4634'-4663'; 4516'-4610'

Date of work _____

Well to be plugged and abandoned as follows:

1. 25 sx plug across perforations 4634'-4663' and 4576'-4610'
2. Recover maximum 5 1/2" casing. Top of cement at 4100'
3. 25 sx plug at casing stub
4. 10 sx plug at 184' (bottom of surface casing)
5. 5 sx plug at surface

Weld on plate and install dry hole marker.

DVR	
FJP	<input checked="" type="checkbox"/>
HHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
GCH	<input checked="" type="checkbox"/>
CGM	

18. I hereby certify that the foregoing is true and correct

SIGNED W.R. Emmett TITLE Area Production Supt. DATE 1/30/75

(This space for Federal or State office use)

APPROVED BY V.V. Rogers TITLE SA DATE FEB 4 1975
CONDITIONS OF APPROVAL, IF ANY: 3-27

CONDITIONS OF APPROVAL, IF ANY: