

# Inspection Photos

2/27/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #334393

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334393



**Photo 1:** Photo taken from the Location entrance on the southwest end of the Location. Photo shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas remain missing or insufficient.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334393



**Photo 2:** See comments under photo 1. Photo shows tracking from Location onto access road.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334393



February 27, 2023

**Photo 3:** Photo taken from the Location entrance on the southwest end of the Location. Photo shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas remain missing or insufficient.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334393



February 27, 2023

**Photo 4:** Photo taken from southeast end of the Location, facing west. Photo shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas remain missing or insufficient.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334393



**Photo 5:** Photo taken from southeast end of the Location, facing northwest. Photo shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas remain missing or insufficient.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC #96850  
Location #334393



**Photo 6:** Photo taken from west end of the Location, facing east. Photo shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas remain missing or insufficient.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334393



February 27, 2023



February 27, 2023

**Photo 7:** Photos taken from the east end of the Location, facing northwest to north. Photos examples showing areas on the north end of the Location that are not reasonably needed for production. Interim reclamation including, but not limited to, removal of gravel/road base, compaction alleviation, replacement of soils and revegetation required.



**Photo 8:** 2009 Google Earth aerial imagery of the Location. Arrow shows unknown equipment existing on the north end of the Location.



**Photo 9:** 2022 Google Earth Aerial imagery. Unknown equipment identified in Photo 8 has been removed. Red Polygon represents a 75' buffer around the northern-most well(s). Northern areas no longer necessary for production.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334393



**Photo 10:** Photos taken from the soil stockpiles along the perimeter of the Location. Vegetation observed on the stockpiles predominantly Undesirable Plant Species such as Annual Wheatgrass, Cheatgrass. Other Undesirable Plant species observed included Halogeton.