

Inspection Photos

2/27/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #334702

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



February 27, 2023

Photo 1: Photos 1- 4 shows that BMPs to stabilize the Location, and to minimize degradation, tracking and sediment transport from the working pad areas remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #334702



February 27, 2023

Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



February 27, 2023

Photo 3: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



February 27, 2023

Photo 4: See comments under photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



Photo 5: Photo taken from southeast end of the Location, facing east. Photo example showing that BMPs to minimize erosion/degradation remain missing on the slopes on the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



February 27, 2023

Photo 6: See comments under photo 5.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #334702



Photo 7: Photos taken from the southeast end of the Location. Photo shows broken marker laying on the ground; marker is now debris; anchor requires proper marking.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



Photo 8: Photos show inadequate anchor marking. Photo also example showing what appears to be liner material observed throughout the interim areas of the Location.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #334702



Photo 9: Photos taken from the separator equipment. Photo shows wooden planks and unused fence panel requiring removal.