

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2023

Submitted Date:

02/13/2023

Document Number:

696204649**FIELD INSPECTION FORM**Loc ID 314835 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		AndrewOlson@chevron.com	
Sanford, Anita		Anita.Sanford@scoutep.com	Rangely Field
,		RangelyRegulatory@scoutep.com	Rangely Field

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229696	WELL	TA	09/01/2020	OW	103-07353	LEVISON 31X	TA

**General Comment:**

On 2/10/2023, Reclamation Specialist Trujillo attempted to inspect Chevron USA's LEVISON #31X Location in Rio Blanco County, Colorado.

Form 9(s) 402887795 transferring Location from Chevron USA to Scout Energy Management #10779 currently "in process"; Chevron remains the Operator on record for the Location until Form 9 is approved.

Inspection is a follow-up to #696204078 to document compliance with the following corrective actions:

- Weeds
- Unused Equipment
- Stormwater

Reclamation Specialist was unable to access Location due to snow. Well Status "TA". A followup inspection will be conducted at a future time when Location becomes accessible.

The following compliance issues were observed during this inspection.

- Inactive Well Requirements.

Refer to the "Location", "Reclamation" and "stormwater" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Location inaccessible due to snow conditions.		
Corrective Action	L	Date:	

Overall Good: ☐

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 229696 Type: WELL API Number: 103-07353 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Records show well has been temporarily abandoned since 9/2020. Pursuant to the Rule 434.c "Plugging Inactive Well" COGCC Operator Guidance, An oil or gas Well that has been temporarily abandoned for a period of 6 consecutive months is considered "Inactive", and requires plugging and abandonment, unless Operator:

A. Brings the Well back to production so that it is no longer an Inactive Well;

B. Files a Form 5B, Inactive Well Notice and provides Single Well Financial Assurance via a Form 3A, Financial Assurance, if required by the Operator's Financial Assurance Plan's requirements related to Low Producing Wells; or

C. Files a Form 6A, Out of Service Designation, to designate the Well as Out of Service pursuant to Rule 434.d.

Corrective Action: **Comply with Rule 434.c**

Date: 03/13/2023

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403319790	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019453">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019453</a>
696204650	Access road impassable.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019433">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6019433</a>