



00572654

UIC

COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT

FAC# 155 API# 061 06036 0 INSPECTOR L. Robbins DATE 7/7/87WELL NAME NW BRANDON UNIT 2-I TYPE E SITE INSPECTION X

FIELD 7500 BRANDON WITNESS MIT _____

OPER 43100 INEXCO OIL CO

LOCATION NENE 5 19.0S 45.0W 6

MAX PERMITTED PRESS 1236 PSI DATE LAST INSPECTION 07/15/86 OUTCOME A

LAST REPORTED PRESS PSI 00/00 DATE LAST MIT 00/00/00

WELL RESTRICTIONS WELL SI 7/78, SURFACE-TBG-NO VALVE

REMEDIAL ACTION

COMPLETION TYPE TP

TUBING PRESSURE

ZONE STLSP

MIT _____ INJECTING _____ PSI

MIT _____ NOT INJECTING SI PSI

TUBING-CASING ANNULUS _____ PSI

BRAIDENHEAD _____ PSI

TOP 4550
BOT 4630

P E R F S

MECHANICAL INTEGRITY TEST

0 MIN. _____ PSI

5 MIN. _____ PSI

10 MIN. _____ PSI

15 MIN. _____ PSI

PRESS CHANGE _____ PSI

CHART USED - YES _____ NO _____

MIT
PACKER
DEPTH _____CASING
SIZE 8 5/8
DEPTH 204SIZE 5 1/2
DEPTH 4817SIZE /
DEPTHSIZE /
DEPTH

PACKER 4511

LINER
TOP
SIZE /
DEPTHPBTVD 4778
TVDACCEPTABLE X NOT ACCEPTABLE _____REMARKS: Flowline has been
disconnected from wellhead
making it inoperable
J Robbins