



00572646



COLORADO OIL AND GAS CONSERVATION COMMISSION - UIC FIELD REPORT

FAC# 155 API# 061 06036 0 INSPECTOR L Robbins DATE 11/7/89WELL NAME NW BRANDON UNIT 2-I TYPE E SITE INSPECTION X

FIELD 7500 BRANDON STATUS SI WITNESS MIT

OPER 67240 PARK OIL & GAS INC

LOCATION NENE 5 19.0S 45.0W 6

MAX PERMITTED PRESS 1236 PSI DATE LAST INSPECTION 12/13/88 OUTCOME A

LAST REPORTED PRESS PSI 08/89 DATE LAST MIT 00/00/00

WELL RESTRICTIONS WELL SI 7/78, SURFACE-TBG-NO VALVE

REMEDIAL ACTION WELL TO REMAIN SHUT-IN UNTIL TESTED

COMPLETION TYPE TP

TUBING PRESSURE

ZONE STLSP

MIT _____ INJECTING _____ PSI

P E R F S

MIT _____ NOT INJECTING SI PSITOP 4550
BOT 4630

TUBING-CASING ANNULUS _____ PSI

BRAIDENHEAD _____ PSI

MECHANICAL INTEGRITY TEST

0 MIN. _____ PSI

5 MIN. _____ PSI

10 MIN. _____ PSI

15 MIN. _____ PSI

PRESS CHANGE _____ PSI

CHART USED - YES _____ NO _____

ACCEPTABLE X NOT ACCEPTABLE _____

REMARKS: Flowline has been
disconnected from well
making it inoperable. Well is
required to be tested or
plugged within six months.

J. RobbinsCASING
SIZE 8 5/8
DEPTH 204SIZE 5 1/2
DEPTH 4817SIZE /
DEPTHSIZE /
DEPTH

PACKER 4511

LINER
TOP
SIZE
DEPTHPBTVD 4778
TVD