

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Wattles on the Northwest corner of the locaiton are not properly installed. Wattles on southwest corner of laciton installed on top of sediment trap berm. Wattles need to be placed in the spillway of the sediment trap.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C. The corrective action date is the date the location was observed out of compliance. It is COGCC's expectation that the corrective action will be addressed immediately.

Date: 02/27/2023

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709400015	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6041700