

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403312318

Date Received:
02/04/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490
Name of Operator: ST CROIX OPERATING INC
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

| Contact Name | Phone | Email |
|--------------------------|-----------------------|---|
| <u>Trisha Fanning</u> | | <u>tfanning@ardorenvironmental.com</u> |
| <u>Andy Peterson</u> | | <u>Andy@Petersonenergyoperating.com</u> |
| <u>Melnychenko, Paul</u> | <u>(303) 489-9298</u> | <u>stcroixexp@aol.com</u> |
| <u>Ryan Dornbos</u> | | <u>Ryan@Petersonenergyoperating.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 696105682
Inspection Date: 01/17/2023 FIR Submit Date: 01/19/2023 FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC Company Number: 81490
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 474453

Location Name: ALICE SEEDORF Number: 1 County: _____
Qtrqr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6
Latitude: 40.123560 Longitude: -102.843830

FACILITY - API Number: 05-121-00 Facility ID: 474453

Facility Name: ALICE SEEDORF Number: 1
Qtrqr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6
Latitude: 40.123560 Longitude: -102.843830

CORRECTIVE ACTIONS:

2 CA# 167063

Corrective Action: Comply with Rule 1002.f.(2) to install and maintain BMPs in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance as the location should be in compliance at all times.

Date: 01/17/2023

Response: CA COMPLETED Date of Completion: 01/17/2023

Operator Comment: The topsoil pile from the original 5" of material stripped was track packed previously, is now frozen, and serves as a BMP protecting the north side of the second topsoil pile. The topsoil piles contain significant clay and are frozen and thus are not subject to wind erosion at this time of year.

2/4/2023 Response

St. Croix restates that interim or final reclamation will occur as soon as weather conditions allow and also restates that frozen soil conditions provide adequate soil compaction to ensure site conditions and controls are adequate and in place to effectively manage stormwater per Rule 1002.f (2) (D).

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: _____

Title: Petroleum Engineer

Date: 2/4/2023 11:56:15 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|-------------------------------|---------------------------|
| 403312318 | FIR RESOLUTION SUBMITTED |

Total Attach: 1 Files