

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/09/2023

Submitted Date:

03/10/2023

Document Number:

702500989

FIELD INSPECTION FORM

Loc ID: 315117 Inspector Name: Burchett, Kirby On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10779
 Name of Operator: SCOUT ENERGY MANAGEMENT LLC
 Address: 13800 MONTFORT DRIVE SUITE 100
 City: DALLAS State: TX Zip: 75240

Findings:

- 11 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatory@scoutep.com	
Patterson, Chris		Chris.Patterson@scoutep.com	
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230282	WELL	SI	06/01/2021	OW	103-07942	FEDERAL 12-6	SI

General Comment:

[COGCC Inspection Report Summary](#)

On Thursday, 03/09/2023, Inspector Kirby Burchett, conducted a routine field inspection at Scout Energy Management LLC on the Federal 12-6, Location #315117, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there, observing normal operations the following compliance issues were found:

1. Well signs need updated.
2. Chemical tank label faded and illegible.
3. Unused equipment on location.

Refer to attached photograph for Corrective Action.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Faded labels on chemical tank. NFPA diamond is illegible		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material and which are required to be marked, placarded, or labeled in accordance with the U.S. Department of Transportation's Hazardous Materials Regulations, will retain the markings, placards, and labels on the Container. Such markings, placards, and labels will be retained on the Container until it is sufficiently cleaned of residue and purged of vapors to remove any potential hazards.		Date: <u>05/15/2023</u>
Type	WELLHEAD		
Comment:	Well signs still identify Whiting Oil and Gas as the operator. Telephone number of current operator not displayed. Transfer of ownership was 7/15/22.		
Corrective Action:	When no associated Tank battery is present at the Oil and Gas Location, the following additional information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); and The public road used to access the Well.		Date: <u>04/10/2023</u>
Emergency Contact Number:			
Comment:	911 is the only valid number displayed. Corrective Action addressed under Signs/Marker: Wellhead		
Corrective Action:			Date:
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Metal guard laying beside pumping unit		
Corrective Action:	The storage, placement, or maintenance of equipment, vehicles, trailers, commercial products, chemicals, drums, totes, containers, materials, and all other supplies not necessary for use on an Oil and Gas Locations is prohibited.		Date: <u>03/20/2023</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Welded wire mesh		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Square tubing		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment: Valves are accessible. Gauge installed.			
Corrective Action:			Date:
Type: Deadman # & Marked # 4			

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on plastic containment		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230282 Type: WELL API Number: 103-07942 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: [Rod pump.](#)
[Last Production - May 2021](#)
[Last Report - June 2022](#)

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Gravel						
Ditches						
Berms						
		Culverts				
				Material Handling And Spill Prevention		

Comment: Limited Stormwater inspection due to location being covered with snow. Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500991	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6046740