



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	NOT ALL CA'S IN INSP. DOC #695107408 HAVE BEEN ADDRESSED. IN THE PREVIOUS INP. THERE WAS A CA TO REMOVE A 1" RISER AFTER LOOKING AT THE PHOTO SUBMITTED BY OPERATOR IN FIRR DOC #403320575 IT APPEARS TO BE A 2" RISER.		
Corrective Action:	REMOVE OR PERMANENTLY MARK RISER PER RULE 606.	Date:	03/15/2023
Type	OTHER		
Comment:	AFTER REMOVING THE CONCRETE SLAB THERE IS A PILE OF MATERIAL LEFT. SEE ATTACT SNIP OF PHOTO SUBMITTED BY OPERATOR.		
Corrective Action:	REMOVE ANY CONTAMINATED MATERIAL AND DISPOSE OF PROPERLY. PERFORM CLEANUP OF MATERIAL LEFT BEHIND (SPREAD MATERIAL OR REMOVE IT) PER RULE 606.	Date:	03/15/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 290023 Type: WELL API Number: 071-09234 Status: PR Insp. Status: PR

**Producing Well**

Comment:		
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP DOC #695107408 IN RESPONSE TO FIRR DOC #403320575, NOT ALL CA'S HAVE BEEN ADDRESSED. SEE HOUSE KEEPING SECTION FOR DETAILS AND ADDITIONAL CORRECTIVE ACTION.	beardsit	03/03/2023

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695107675	PHOTO SUBMITTED BY OPERATOR	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6051733">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6051733</a>