

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403350068

Date Received:
03/20/2023

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10670

Name of Operator: BISON IV OPERATING LLC

Address: 518 17TH STREET SUITE 1800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Katie Gillen

720-644-6997

kgillen@bisonog.com

Tarah Garza

970-692-1963

tgarza@bisonog.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200026

Inspection Date: 03/08/2023

FIR Submit Date: 03/13/2023

FIR Status: _____

Inspected Operator Information:

Company Name: BISON IV OPERATING LLC

Company Number: 10670

Address: 1400 16TH STREET SUITE 300

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 455365

Location Name: Shoveler Number: Pad County: _____

Qtrqr: NENW Sec: 29 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.638448 Longitude: -104.118002

FACILITY - API Number: 05-123- -00 Facility ID: 455365

Facility Name: Shoveler Number: Pad

Qtrqr: NENW Sec: 29 Twp: 8N Range: 60W Meridian: 6

Latitude: 40.638448 Longitude: -104.118002

CORRECTIVE ACTIONS:

1 CA# 168065

Corrective Action: Comply with Rule 606 and remove debris.

Date: 03/20/2023

Response: CA COMPLETED

Date of Completion: 03/17/2023

Operator Comment: Debris removed.

COGCC Decision: _____

COGCC
Representative:

2 CA# 168066

Corrective Action: Install or repair wildlife protection equipment per Rule 902.b.

Date: 03/23/2023

Response: CA COMPLETED

Date of Completion: 03/17/2023

Operator
Comment: Netting repaired. See attached photos.

COGCC Decision:

COGCC
Representative:

3 CA# 168067

Corrective Action: Perform reclamation in accordance to Rule 1003. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Corrective action date is the date the location was observed out of compliance.

Date: 03/08/2023

Response: CA COMPLETED

Date of Completion: 03/17/2023

Operator
Comment: See attached photos

COGCC Decision:

COGCC
Representative:

4 CA# 168068

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C.

Date: 03/15/2023

Response: CA COMPLETED

Date of Completion: 03/17/2023

Operator
Comment: See attached photos.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Lauren Morahan

Signed:

Title: Regulatory Manager

Date: 3/20/2023 11:23:05 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403350107	Shoveler corrective action photos 3.17.23

Total Attach: 1 Files