



121-05643

RECEIVED

COLO. OIL & GAS CONS. COMM. THE STATE OF COLORADO

JUN 3 1968

99999999

Indicate for Patented and Federal lands. Use "APPLICATION FOR PERMIT—" for such proposals.

COLO. OIL & GAS CONS. COMM.

5. LEASE DESIGNATION AND SERIAL NO.

Fee Land

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pierce

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Big Beaver

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 9, T3S, R56W

12. COUNTY OR PARISH

Washington

13. STATE

Colorado

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL [X] GAS WELL [] OTHER []

2. NAME OF OPERATOR Continental Oil Company

3. ADDRESS OF OPERATOR 200 North Wolcott, Casper, Wyoming 82601

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 660' FSL, 1980' FWL At proposed prod. zone

dissect

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4669' RB 4659' Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF [] PULL OR ALTER CASING [] FRACTURE TREAT [] MULTIPLE COMPLETE [] SHOOT OR ACIDIZE [] ABANDON [X] REPAIR WELL [] CHANGE PLANS [] (Other) []

WATER SHUT-OFF [] REPAIRING WELL [] FRACTURE TREATMENT [] ALTERING CASING [] SHOOTING OR ACIDIZING [] ABANDONMENT [] (Other) []

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Date of work _____

A notice of intention to drill a replacement hole for this well will be submitted as soon as survey plats are made available. Pierce No. 2 will be plugged and abandoned as follows:

A cement plug will be spotted on top of dropped tubing. Casing will be cut off at or near 4000'. This is slightly above the Niobrara top at 4119', which controls pipe recovery. A cement plug will be spotted over the cut-off stub. The base of the surface pipe will be cemented. Mud-laden fluid will be used between cement plugs. Surface will be cemented with a casing marker according to regulations.

Table with 2 columns and 5 rows, containing checkmarks in the right column.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Administrative Section Chief DATE May 31, 1968

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE DIRECTOR O & G CONS. COMM. DATE JUN 4 1968

CO&GCC(3) WCB RCB



00229627