

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/04/2022

Submitted Date:

10/05/2022

Document Number:

690203460

## FIELD INSPECTION FORM

Loc ID 333511 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

## Operator Information:

OGCC Operator Number: 10705

Name of Operator: EVERGREEN NATURAL RESOURCES LLC

Address: 1875 LAWRENCE ST STE 1150

City: DENVER State: CO Zip: 80202

## Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response RequestedANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:


Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264414	WELL	PR	09/09/2009	GW	071-07696	BULL DEEP 42-10	RI

## General Comment:

This is a stormwater management inspection. See attached photos and additional details within this report.

 EVERGREEN NATURAL RESOURCES	<b>COGCC Work Order</b>	<b>Stormwater: Roustabout</b>
<b>COGCC Submitted Date:</b>	<b>Document #</b>	<b>COGCC Deadline Date:</b>
10/4/2022	690203460	11/4/2022
<b>Contractor Assigned:</b>	<b>Well Name:</b>	
	Bull Deep 42-10	
<b>Contractor Completion Signature:</b>	<b>Contractor Completion Date:</b>	
<b>Foreman Completion Signature:</b>	<b>Foreman Completion Date:</b>	
Contractor and Foreman must sign upon completion. Please email Susan at <a href="mailto:susan.wolfram@enrllc.com">susan.wolfram@enrllc.com</a> and attach <u>Field Ticket and Photos</u>		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion occurring across the access road in a drainage area. This area has no culvert and stormwater from the drainage washes across the road.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 11/04/2022

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690203461	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878814">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5878814</a>