



RECEIVED

JUN 13 1983

COLO. OIL & GAS CONS. COMM.

STATE PLUGGING REPORT

J. W. GIBSON WELL SERVICE COMPANY

Well Name Stenback #2

Location SW/SW Sec. 15-T3S R55W

Operator Patrick A. Doheny

This well was filled with Wt. 9.9 Mud.

_____ sacks were put @ _____.

20 sacks were put at the bottom of surface pipe and

10 sacks at the top of the surface pipe.

Yes No Steel cap was put on surface casing.

To my knowledge, no junk was left in the hole.

Remarks: _____

Plugging orders were received from Frank Piro

Signed,

J. W. GIBSON WELL SERVICE COMPANY

David Heisel

TIME: 6:30 A.M. P.M.

DATE: 5-6-83

jr
6-17-83

RECEIVED

MAY 19 1983

BY _____