



99999999

OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- (121 - 08548)		LEASE NAME: Landaker #1	
LOCATION: SWSE 18-35-55		OPERATOR: H+R	
DATE: 9-30-96		INSPECTOR: EBBWiley	
Insp. Type: CA	Insp. Status: PA	PA: Y (N)	Pass/Fail: P (F)
		Viol.: Y (N)	NOV: Y (N)

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	Well cemented by H+R	—
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	Larry Musgrave operator	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)	H+R W/S.	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	incomplete	
Miscellaneous		

CORRECTIVE ACTION REQUIRED: Remove equipment at site and battery, restore within 6 months —

Date Corrective Action Required By: 3-30-97 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00325581

White - File Canary - Operator Pink - Well Site