

Location

Lease Road:			
Type	Access		
comment:	PHOTO 1: NO ACCESS NO PIONEER LOCK ON GATE, CURRENT COMBO FOR THE McCLAREN 2470 DOES NOT WORK ON THE LOCK.		
Corrective Action:	PROVIDE COGCC ACCESS TO THIS GATE PER RULE 204.	Date:	04/08/2023

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	<input style="width: 100%;" type="text"/>

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

Flaring:

Type			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>	Date:	<input style="width: 100%;" type="text"/>

Inspected Facilities

Facility ID: 259433 Type: WELL API Number: 071-07249 Status: PR Insp. Status: PR

Producing Well

Comment:			
Corrective Action:			Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695107865	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6066096