

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403352408

Date Received:
03/22/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490
Name of Operator: ST CROIX OPERATING INC
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Melnychenko, Paul</u>	<u>(303) 489-9298</u>	<u>stcroixexp@aol.com</u>
<u>Peterson, Andy</u>	<u>970-203-4263</u>	<u>andy@petersonenergyoperating.com</u>
<u>Dornbos, Ryan</u>	<u>303-915-9074</u>	<u>ryan@petersonenergyoperating.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200022
Inspection Date: 03/03/2023 FIR Submit Date: 03/09/2023 FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC Company Number: 81490
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 474453

Location Name: ALICE SEEDORF Number: 1 County: _____
Qtrqtr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6
Latitude: 40.123560 Longitude: -102.843830

FACILITY - API Number: 05-121-00 Facility ID: 474453

Facility Name: ALICE SEEDORF Number: 1
Qtrqtr: NESW Sec: 22 Twp: 2N Range: 49W Meridian: 6
Latitude: 40.123560 Longitude: -102.843830

CORRECTIVE ACTIONS:

1 CA# 167980

Corrective Action: Clean up stained soil Per Rule 1002.f(2)D. Date: 03/15/2023

Response: CA COMPLETED Date of Completion: 03/16/2023

Operator Comment: On 03/16/2023 the stained soil under the BOP accumulator trailer was cleaned up and disposed of and the trailer has been removed from the location.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no photo documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 167981

Corrective Action: Comply with Rule 1002.f.(2) to install and maintain BMPs in accordance with good engineering practices. Corrective action date is the date the location was observed out of compliance as the location should be in compliance at all times. Operator shall continue to control and manage stormwater BMP until final reclamation is achieved pursuant to Rule 1004.

Date: 01/17/2023

Response: CA COMPLETED

Date of Completion: 03/16/2023

Operator Comment: On the 03/16/2023, the location was evaluated for maintenance of BMPs and all soil surrounding the location was waterlogged and the edges of location are still too wet and soft to compact. The additional disturbance that would be created attempting to compact would create un-necessary damage and would not result in additional control of the already immobilized soil due to the moisture content.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dornbos

Signed: _____

Title: Petroleum Engineer

Date: 3/22/2023 8:45:10 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

403352408	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files