

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403352414

Date Received:
03/22/2023

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 81490
Name of Operator: ST CROIX OPERATING INC
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Melnychenko, Paul</u>	<u>(303) 489-9298</u>	<u>stcroixexp@aol.com</u>
<u>Dornbos, Ryan</u>	<u>303-915-9074</u>	<u>ryan@petersonenergyoperating.com</u>
<u>Peterson, Andy</u>	<u>970-203-4263</u>	<u>andy@petersonenergyoperating.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 708200024
Inspection Date: 03/03/2023 FIR Submit Date: 03/09/2023 FIR Status: _____

Inspected Operator Information:

Company Name: ST CROIX OPERATING INC Company Number: 81490
Address: P O BOX 13799
City: DENVER State: CO Zip: 80201

LOCATION - Location ID: 482780

Location Name: Horseshoe Number: 1 County: _____
Qtrqtr: NENE Sec: 27 Twp: 3S Range: 49W Meridian: 6
Latitude: 39.768700 Longitude: -102.843070

FACILITY - API Number: 05-121-00 Facility ID: 482780

Facility Name: Horseshoe Number: 1
Qtrqtr: NENE Sec: 27 Twp: 3S Range: 49W Meridian: 6
Latitude: 39.768700 Longitude: -102.843070

CORRECTIVE ACTIONS:

1 CA# 167982

Corrective Action: This location should have been in compliance during the construction phase. At this stage, if this location does not restore properly following the first growing season after seeding, the Operator will be required to import new topsoil to ensure that the location reaches uniform vegetation cover in accordance with 1004 Rules.

Note: This corrective action will remain in place to monitor the success of the revegetation.

Date: _____

Response: CA COMPLETED

Date of Completion: 03/14/2023

Operator Comment: As of 03/14/2023 the location has been restored to grade and all stockpiled soils have been pushed back to their initial location. The location was cross-ripped to de-compact and is ready to be re-seeded with a seed-mix approved by the land owner. The location was re-seeded March 20, 2023 and will be monitored for growth.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

2 CA# 167983

Corrective Action: Comply with Rule 1002.c. Corrective action date is the date the location was observed out of compliance.

Date: 03/03/2023

Response: CA COMPLETED

Date of Completion: 03/14/2023

Operator Comment: As of 03/14/2023 the location has been restored to grade and all stockpiled soils have been pushed back to their initial location. The location was cross-ripped to de-compact and is ready to be re-seeded with a seed-mix approved by the land owner. The location was re-seeded March 20, 2023 and will be monitored for growth.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

3 CA# 167984

Corrective Action: Immediately install or repair required BMPs per Rule 1002.f. in accordance with good engineering practices.

The corrective date is not intended to be the date for which the Operator shall complete the corrective actions but rather the corrective date is the date the location was observed out of compliance, as it should be in compliance at all times.

Date: 01/09/2023

Response: CA COMPLETED

Date of Completion: 03/14/2023

Operator Comment: As of 03/14/2023 the location has been restored to grade and all stockpiled soils have been pushed back to their initial location. The location was cross-ripped to de-compact and is ready to be re-seeded with a seed-mix approved by the land owner. The location was re-seeded March 20, 2023 and will be monitored for growth.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ryan Dombos

Signed: _____

Title: Petroleum Engineer

Date: 3/22/2023 8:41:28 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403352414	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files