

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2023

Submitted Date:

03/30/2023

Document Number:

695107953

FIELD INSPECTION FORM

Loc ID 307532 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
 Name of Operator: EVERGREEN NATURAL RESOURCES LLC
 Address: 1875 LAWRENCE ST STE 1150
 City: DENVER State: CO Zip: 80202

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217792	WELL	PR	11/04/1998	CBM	071-06571	BROWN BEAR 44-07	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Type: Bradenhead

1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment:

Corrective Action:

Date:

Type: Deadman # & Marked

4

Comment:

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Fail			

Comment: [PHOTO 4: STORM WATER EROSION ON BYPASS TURN ROAD JUST NORTH OF LOCATION.](#)

Corrective Action: **REPAIR ROAD AND INSTALL BMP[S TO PREVENT THIS TYPE OF EROSION PER RULE 1002.**

Date: 04/30/2023

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 117464 Lat: 37.093644 Long: -104.706024

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Fencing:

Fencing Type: None Fencing Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695107954	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6067623