

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2023

Submitted Date:

03/27/2023

Document Number:

691201651**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Graber, Candice (Nikki) 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Meis, Craig		cmeis@kpk.com	KPK Environmental
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
Leonard, Mike		mike.leonard@state.co.us	

General Comment:

COGCC environmental inspection to determine progress on Spill ID 482625. This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Incident information:

Spill Discovery Date: 7/25/2022

Days open: 235 days

Last report: 403330347 submitted 03/15/2023 requesting backfill was denied as impacts remain both on sidewall and floors requiring additional remediation. Form 19 has been open greater than 90 days, Operator is out of compliance with Rule 912.b.(6)

Current site status: Excavation open, impacts in situ, fencing present.

Location**Lease Road:**

Type	Access		
comment:	Drive through pit entrance to access. Spill is within raceway parking lot.		
Corrective ActionL		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Form 19 has been open greater than 90 days, Operator is out of compliance with Rule 912.b.(6)

Corrective Action: Pursuant to Rule 912.b.(6) Operator was required to submit a Form 19 Supplemental Report for the associated spill within 90 days of the spill date requesting closure. The Form 19 Supplemental Report for closure was due by Oct 23, 2022.

Date: 10/23/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Spill/Remediation:

Comment: Excavation is open and impacts are in situ both on sidewall and floors requiring additional remediation. There were no operator or contract environmental personnel on location at the time of this field inspection.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403356617	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6063075
691201652	Excavation overview	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6063074