

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2023

Submitted Date:

04/03/2023

Document Number:

696204806

FIELD INSPECTION FORM

Loc ID 322356 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 51130
Name of Operator: LOCIN OIL CORPORATION
Address: 600 TRAVIS ST STE 6161
City: HOUSTON State: TX Zip: 77002

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
		dbenedict@locin.energy	
		hsirvent@locinoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210351	WELL	TA	12/29/2021	GW	045-06107	FEDERAL 27-11	RI

General Comment:

On 3/31/2023, Reclamation Specialist Trujillo attempted to inspect Locin Oil Corporations' FEDERAL #27-11 Location in Garfield County, Colorado.

Location was inaccessible due to a stock pond overflowing onto the access road: a followup inspection will be required to determine compliance with Rules and Corrective Actions.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location

Lease Road:			
Type	Access		
comment:	<p>Location was inaccessible due to a stock pond overflowing onto the access road: a followup inspection will be required to determine compliance with Rules and Corrective Actions.</p> <p>It is being noted that, though Operator has failed to maintain the road in a manner to allow access in accordance with Rule 204, records show the well is currently "TA".</p> <p>A followup inspection will be conducted to determine compliance with COGCC Rules and Corrective Actions.</p>		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 90%;" type="text"/>
Corrective Action:	<input style="width: 90%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210351 Type: WELL API Number: 045-06107 Status: TA Insp. Status: RI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Records show Well has been TA since December 2021.

Form 21 #402911481 submitted 12/29/2021 shows MIT conducted 12/21/2021 failed; Form states Well will be plugged.

Operator submitted Form 21 #403169200 on 9/29/2022 showing Well Failed a second MIT; Form states Well will be plugged.

Operator submitted Form 6(N) #403121745 on 9/29/2022.

Inspection #693805279 on 11/14/2022 observed that Plugging Operations have not begun.

Pursuant to Rule 417.f, wells that fail an MIT require repairing or plugging within 6 months of failure- Well required plugging or repairment by June 2022.

No other records on file indicating that the Well has been PAd and Facilities Closed per 911.a.

A followup inspection will be conducted to determine compliance with COGCC Plugging and Facility Closure requirements.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696204807	Access road flooded	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070623