

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2023

Submitted Date:

04/03/2023

Document Number:

702501053

FIELD INSPECTION FORMLoc ID 315170 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 34720

Name of Operator: GORDON ENGINEERING INC

Address: PO BOX 3525

City: GRAND JUNCTION State: CO Zip: 81502

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Bryan, Nicholas	(385) 250-4548	nickbryan85@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
103788	PIT	AC	09/16/2022		-	FEDERAL 10-4 SEPARATOR	AC
230362	WELL	PR	10/01/2021	GW	103-08024	FEDERAL 10-4	PR

General Comment:**COGCC Inspection Report Summary**

On Monday, 04/03/2023, Inspector Kirby Burchett, conducted a follow up field inspection at Gordon Engineering Inc. on the Federal 10-4 well, Location #315170, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District Wildlife Management Area with Black Bear/High Priority/NSO/Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

Corrective Actions from Inspection #702500900 on 2/21/2023 have not been addressed.

While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1. Bradenhead inaccessible or not visible.
2. Stormwater BMPs have not been implemented.

Refer to Inspection Photos for observed compliance issue.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 / (970) 618-0811	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PIT		
Comment:	Woven wire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration card indicates the most recent calibration is within the past year.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.		Date: 04/18/2023

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	103788	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	AC
Facility ID:	230362	Type:	WELL	API Number:	103-08024	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Free flow								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Location lacks stabilization. No Stormwater BMPs have been implemented. BLM road crosses location.
Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Corrective Action: Provide proper BMPs to prevent sediment migration from location.

Date: 04/18/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: 103788 Lat: 39.886953 Long: -108.725361

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Corrective Action _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: _____

Corrective Action _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501056	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6070746