


Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC Diamond Elk, LLC /GV 84-1

Location #: 335008



Location Overview: Location is located in a High priority habit area.

Section/Township/Range: 1 7S95W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Diamond Elk, LLC /GV 84-1
Location #: 335008



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Diamond Elk, LLC /GV 84-1
Location #: 335008



Photo #9504 Location lacks stabilization.



Photo #9505 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Diamond Elk, LLC /GV 84-1
Location #: 335008



Photo #9506 Location lacks stabilization.



Photo #9507 Location lacks stabilization.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC Diamond Elk, LLC /GV 84-1
Location #: 335008



Photo #9524 Insufficient tracking BMP at entrance to location.



Photo #9525 Insufficient tracking BMP at entrance to location.