

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 40-20 Pad

Location ID: 335154



Photo # 4252 From entrance to location



Photo # 4253 From entrance to location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 40-20 Pad

Location ID: 335154



Photo # 4254 Location



Photo # 4255 Location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 40-20 Pad

Location ID: 335154



Photo # 4256 Location



Photo # 4257 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 40-20 Pad

Location ID: 335154



Photo # 4259 Containment liner needs maintenance



Photo # 4261 Containment liner needs maintenance

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 40-20 Pad

Location ID: 335154



Photo # 4262 Containment liner needs maintenance



Photo # 4263 Containment capacity inadequate/Failure to maintain containment