

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2023

Submitted Date:

04/04/2023

Document Number:

702501071

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 316438 \_\_\_\_\_ Burchett, Kirby \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 OGCC Operator Number: \_\_\_\_\_ 16700 \_\_\_\_\_  
 Name of Operator: CHEVRON USA INC \_\_\_\_\_  
 Address: 760 HORIZON DRIVE STE 401 \_\_\_\_\_  
 City: GRAND JUNCTION \_\_\_\_\_ State: CO \_\_\_\_\_ Zip: 81506 \_\_\_\_\_
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 \_\_\_\_\_ Number of Comments
- 1 \_\_\_\_\_ Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us	
Patterson, Chris		Chris.Patterson@scoutep.com	
Sanford, Anita	(970) 551-8313	Anita.Sanford@scoutep.com	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274584	WELL	PR	09/01/2022	OW	103-10532	ASSOCIATED UNIT A 2X	PR

**General Comment:**[COGCC Inspection Report Summary](#)

On Tuesday, 04/04/2023, Inspector Kirby Burchett, conducted a routine field inspection at Chevron USA Inc. (Scout Energy Partners) on the Associated Unit A 2X, Location #316438, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority and Density Habitats.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal production operations the following compliance issue was observed:

1. Stormwater BMP maintenance. Location berm breached.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911 / (970) 675-3700		
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:		Date:			
Type: Bradenhead	# 1				
Comment:	Valve is accessible. Gauge installed. Line hooked up to flowline.				
Corrective Action:		Date:			
Type: Submersible Pump	# 1				
Comment:					
Corrective Action:		Date:			
Type: Ancillary equipment	# 1				
Comment:	Chemical tank on plastic containment stand.				
Corrective Action:		Date:			

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 274584 Type: WELL API Number: 103-10532 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Submersible pump.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
				Material Handling And Spill Prevention		
		Ditches				
Berms	Fail					Berm breached in areas
		Culverts				

Comment: Road maintenance pulls loose sediment on to roadway creating vehicle tracking issues during wet conditions.

Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation.

Oil and gas operators shall implement and maintain vehicle tracking Best Management Practices (BMPs) to control potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action: **Provide proper BMPs to prevent sediment migration from location and lease road.**

Date: 04/20/2023

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702501073	inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072350">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6072350</a>