

<b>NON-HAZARDOUS WASTE MANIFEST</b>		Generator's EPA ID No.	Profile No.	Page 1 of 1	<b>PAWNEE WASTE LLC</b>	
Generator's Name and Mailing Address:	<i>McCarney Energy LLC</i>			Manifest No.:		
				No 182014		
	Designated Facility Name and Site Address:		Weld County USR No.:	Facility Phone No.:		
	Pawnee Waste 47368 County Rd 118 Grover, CO 80729		USR15-0048	(970) 889-0006		
	Well or Site Name:			Truck/Haul Container	Total Quantity	Unit/Wt/Vol
	<i>SJ Warren #1</i>			Net	Type:	
AFE# / Reference#:			<i>871</i>	<i>P/U DT</i>	<i>3 tons</i>	
Lat/Long:			Waste Name/Waste Type:			
			<i>dry soil with hydrocarbons</i>			
Special Handling Instructions:						
Generator's Certification: I certify the materials described above on this manifest are not subject to federal regulations for reporting proper disposal of Hazardous Waste						
Printed/Typed Name:		Signature:		Date:		
Transporter Acknowledgment of Receipt of Materials	Transporter Company Name:		US EPA ID No.:	Transporter's Phone No.: (include area code)		
	<i>X DY SERVICE LLC</i>					
	Printed/Typed Name:		Signature:		Date:	
<i>Levi Dixon</i>		<i>[Signature]</i>		<i>2-3-24-2023</i>		
Bill To Company Name: (if invoicing is other than the Generator Company listed above)	<i>LDY Services LLC</i>					
	Discrepancy Indication Space:					
	Waste Load Rejection Reason: (complete and attach waste rejection form to facility manifest copy)					
	Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as noted above					
	Printed/Typed Name:		Signature:		Date:	
<i>Josh Gault</i>		<i>[Signature]</i>		<i>3/24/23</i>		